


Nakrętki do zgrzewania Typ T – Forma B



MATERIAŁY:

- Stal
- Stal nierdzewna A2

POWŁOKA:

- Bez pokrycia S

gwint	d1	d	h	b
M3	–	17	6,0	9
M3,5	4.1	17	5,0	9
M4	4.9	17	6,0	9
M5	6.1	19	7,5	11
M6	7.0	19	7,5	11
M6	7.5	22	8,5	14
M8	9.0	22	8,5	14
M8	9.7	26	11,0	18
M10	11.5	26	10,5	18